*	Approved For Release 2006/12/19 : CIA-RDP89B00569R000400140210-9  25X1			
ORIG :	7	CLASSIFIED MESSAGE	The second secon	ROUTING
UNIT:	DPD/OPS/PLANS	ROULING	1 OFS (DPD	4 AC/DPD
5X1 <b>EXT</b> :		CH/OPS BR T	2 OPS/DPD	5 DPD/RI
DATE :	26 JAN 61	COMMO	MAT/DPD	161
то :		115011	1	
FROM:	25X1	CH/AIR OPS		
	DIRECTOR	PRGar 22 3	R .	INITIA
CONF:	DPD (1-2-3-4-5-6-7-8-9	AIR SJPPORT	DEFERRED	PRIORITY
INFO :	S/C (11)	INTEL	ROUTINE	OPERATIONAL INITIA
	RAS	GONTROL (		
5X1	TOR: 1615Z 26 JAN 61			OUT81527
<b>70</b> 25X1	(OPIN)	LOPENT)	crie L	25X1 25X1
	REF: A.	101 101 1V	Oile	:7155
5X1		1		
	<b>B.</b>	J		
	1. IN ORDER TO CLARIFY POSSIBLE CAUSES SUDDEN ERRATIC PROBLEMS FUEL SYSTEMS			
	REQUEST ANSWERS FOLG:			
		ENOID VALVE WIRED TO REMA		,
5X1 	THIS VALVE SHOULD BE ENERGIZED OPEN FOR ALL FLYING WITH SLIPPER TANKS.			
	B. HAS GROUND CHECK BEEN MADE TO DETERMINE THAT AIR IS COMING THRU LINE			
j	FROM ENGINE TO SLIPPER	TANKS? THIS CAN BE DONE	BY DISCONNECTING	AIR LINE TO
Q	SLIPPER TANKS AT REAR BEAM AND THEN RUNNING ENGINE.			
	C. IF A AND B ABOVE AFFIRMATIVE, HAS ANY CHANGE BEEN MADE WHICH MICHT			
	ACCOUNT FOR ERRATIC FEEDING ON TWO TEST FLIGHTS AT 25X1			
	D. HAS ANY WORK BEEN DONE ON ELECT SYSTEM WHICH COULD HAVE CAUSED A			
		IRE TO THE FUEL COUNTER TO		MATIC ACTION OF
	13	CAUSED BY GROUNDING WRONG		
25X1	2. REQUEST REPLY TO ABO	OVE QUESTIONS REACH HOS PR	RIOR 26/2030Z 80	FURTHER
	QUESTIONS CR ADVICE CAN BE G			and return
	genration	COORDINATING OFFICERS		
	RELEASING OFFICER	OP SECRET	AUTHENTIC	ATING OFFICER
	KEPRODUCTION BY OTH	HER THAN THE ISSUING OFFIC	CE IS PROHIBITED.	Copy No.

